**S&MA Mission Services Task Directive** Control No. PROJECT SYMBOL ORG No.: Contract No. 0110 GP-B QS30-S NAS8-00179 Originator's Signature: Date: Originator's Priority: Sonia Bernier High Office Manager's Signat Chris Cowart COTR's Approval: Subject: Additional Safety & Mission Assurance support for the Gravity Probe B (GP-B) Project to include on-site QA support at Stanford University and reliability support for redesign gas module

#### Task Description:

#### Quality (PWS Section 6.0) on-site at Stanford

- 1) Support Product Development Team
- 2) Participate in Milestone Reviews
- 3) Evaluate inspection criteria
- 4) Support failure and problem analyses, MRB, and the non-conforming materials process for hardware
- 5) Support internal and external audits
- 6) Evaluate test plans and procedures and witness testing of hardware and software
- 7) Evaluate project and project related plans and procedures

## R&M (PWS Section 5.0)

- 1) Review subcontractor FMEA/CIL
- 2) Develop fault tree to support investigations or design

### Project Assurance (PWS Section 8.0)

- 1) Participate in the milestone reviews for redesigned hardware
- 2) Coordinate with the on-site quality support at Stanford as required
- 3) Coordinate the development of Fault Tree Analysis (FTA) performed by discipline

# **S&MA Mission Services Task Directive**

Contro	No. 0110	PROJECT SYMBOL: GP-B	Contract No. NAS8-00179
Delive	erables:		
	Review comn plans, etc.	nents for Milestone Review documents	ation, project plans, procedures, drawings, process
2)	_	riew comments to Milestone Review d nents on contractor FMEA/CIL or Re lysis	
1)		n contractor as appropriate tion as required	
Sched	dules/Duratio	on:	
1) <i>2)</i>	Additional su Launch FY03	pport to begin April 1, 2002 and exte	nd through May 31, 2003.
Resou	urce Estimate	e:	
(b)(4)			
	Progress To: S&	MA Project Lead	Frequency of Report:

Weekly